









## RELATIVE HUMIDITY AND TEMPERATURE PROBES

Code	Sensors	Range RH - Temp.	
HP472ACR	RH Pt100	5 ÷ 98% RH -20°C...+80°C	
HP572ACR	RH TC.K		
HP473ACR			
HP474ACR		5 ÷ 98% RH -40°C...+150°C	
HP475ACR	RH Pt100		
HP475AC1R			
HP477DCR			
HP478ACR			

## SATURATED SOLUTIONS AND PROBE PROTECTIONS

CODE			USE
HD75 HD33 HD11	Threaded ring nut M24 x 1,5 for probes Ø 26 Threaded ring nut M12 x 1 for probes Ø 14		
P1 P2 P3 P4	Ø 26	M 24x1,5	
P5 P6 P7 P8	Ø 14	M 12x1	